




# HL310Prblue-3121 < 0,50 l/sec DN 50/75/110



**D** BODENABLAUF  
**IT** SCARICO A PAVIMENTO  
**GB** FLOOR DRAIN




**TR** YER SÜZGEÇİ  
**CZ/SK** PODLAHOVÁ VPUST  
**HR** PODNI ODVOD

**HU** PADLÓLEFOLYÓ  
**PL** WPUST PODŁOGOWY  
**SI** TALNI ODTOK

**RO** SIFON DE PARDOSEALĂ  
**RU** ТРАП  
**BG** ПОДОВ СИФОН

27.02.2024

# HL310Prblue-3121 < 0,50 l/sec DN 50/75/110



**D** BODENABLAUF  
**IT** SCARICO A PAVIMENTO  
**GB** FLOOR DRAIN




**TR** YER SÜZGEÇİ  
**CZ/SK** PODLAHOVÁ VPUST  
**HR** PODNI ODVOD

**HU** PADLÓLEFOLYÓ  
**PL** WPUST PODŁOGOWY  
**SI** TALNI ODTOK

**RO** SIFON DE PARDOSEALĂ  
**RU** ТРАП  
**BG** ПОДОВ СИФОН

27.02.2024

# HL310Prblue-3121 < 0,50 l/sec DN 50/75/110



**D** BODENABLAUF  
**IT** SCARICO A PAVIMENTO  
**GB** FLOOR DRAIN




**TR** YER SÜZGEÇİ  
**CZ/SK** PODLAHOVÁ VPUST  
**HR** PODNI ODVOD

**HU** PADLÓLEFOLYÓ  
**PL** WPUST PODŁOGOWY  
**SI** TALNI ODTOK

**RO** SIFON DE PARDOSEALĂ  
**RU** ТРАП  
**BG** ПОДОВ СИФОН

27.02.2024

# HL310Prblue-3121 < 0,50 l/sec DN 50/75/110



**D** BODENABLAUF  
**IT** SCARICO A PAVIMENTO  
**GB** FLOOR DRAIN

**TR** YER SÜZGEÇİ  
**CZ/SK** PODLAHOVÁ VPUST  
**HR** PODNI ODVOD

**HU** PADLÓLEFOLYÓ  
**PL** WPUST PODŁOGOWY  
**SI** TALNI ODTOK

**RO** SIFON DE PARDOSEALĂ  
**RU** ТРАП  
**BG** ПОДОВ СИФОН

27.02.2024