





# HL510Prblue-3123 < 0,50 l/sec DN 40/50



**D** BODENABLAUF  
**IT** SCARICO A PAVIMENTO  
**GB** FLOOR DRAIN  
**TR** YER SÜZGEÇİ  
**CZ/SK** PODLAHOVÁ VPÚST  
**HR** PODNI ODVOD  
**HU** PADLÓLEFOLYÓ  
**PL** WPÚST PODLOGOWY  
**SI** TALNI ODTOK  
**RO** SIFON DE PARDOSEALĂ  
**RU** ТРАП  
**BG** ПОДОВ СИФОН

27.02.2024



# HL510Prblue-3123 < 0,50 l/sec DN 40/50



**D** BODENABLAUF  
**IT** SCARICO A PAVIMENTO  
**GB** FLOOR DRAIN  
**TR** YER SÜZGEÇİ  
**CZ/SK** PODLAHOVÁ VPÚST  
**HR** PODNI ODVOD  
**HU** PADLÓLEFOLYÓ  
**PL** WPÚST PODLOGOWY  
**SI** TALNI ODTOK  
**RO** SIFON DE PARDOSEALĂ  
**RU** ТРАП  
**BG** ПОДОВ СИФОН

27.02.2024



# HL510Prblue-3123 < 0,50 l/sec DN 40/50



**D** BODENABLAUF  
**IT** SCARICO A PAVIMENTO  
**GB** FLOOR DRAIN  
**TR** YER SÜZGEÇİ  
**CZ/SK** PODLAHOVÁ VPÚST  
**HR** PODNI ODVOD  
**HU** PADLÓLEFOLYÓ  
**PL** WPÚST PODLOGOWY  
**SI** TALNI ODTOK  
**RO** SIFON DE PARDOSEALĂ  
**RU** ТРАП  
**BG** ПОДОВ СИФОН

27.02.2024

# HL510Prblue-3123 < 0,50 l/sec DN 40/50



**D** BODENABLAUF  
**IT** SCARICO A PAVIMENTO  
**GB** FLOOR DRAIN  
**TR** YER SÜZGEÇİ  
**CZ/SK** PODLAHOVÁ VPÚST  
**HR** PODNI ODVOD  
**HU** PADLÓLEFOLYÓ  
**PL** WPÚST PODLOGOWY  
**SI** TALNI ODTOK  
**RO** SIFON DE PARDOSEALĂ  
**RU** ТРАП  
**BG** ПОДОВ СИФОН

27.02.2024