

Product discontinuation

HL800 Pipe sleeve with PVC flange for pipes

The product discontinuation affects the HL800 Pipe sleeve with PVC flange for series.

The following products are affected.

HL800P/40-50	Pipe sleeve DN40-50 with PVC flange for pipes
HL800P/63-75	Pipe sleeve DN63-75 with PVC flange for pipes
HL800P/110	Pipe sleeve DN110 with PVC flange for pipes
HL800P/125	Pipe sleeve DN125 with PVC flange for pipes
HL800P/160	Pipe sleeve DN160 with PVC flange for pipes
HL800P.2/40-50	Double pipe sleeve DN40-50 with PVC flange for pipes
HL800P.2/63-75	Double pipe sleeve DN63-75 with PVC flange for pipes

Please note:

The **HL800 sealing kit with bitumen collar** will remain in the product range and continues to be available.

Discontinuation effective: immediately

Existing stock will be sold while supplies last.